46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**GX69VTA**

## Volkswagen Tiguan 2.0 TDi 190 4Motion Match 5dr DSG

nama GRADE 4

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Margin |
| **V5** | Present |

### Details

| | | | | | |
|---|---|---|---|---|---|
| **Reg. date** | 30/09/2019 | **Body Style** | Estate | **Last service miles** | 63,650 |
| **Year** | 2019 | **Keys** | 2 | **MOT Due** | 16/08/2027 |
| **Mileage** | 67,675 Miles Warranted | **Service history** | Yes | **Gearbox** | SEMI AUTO |
| **Fuel Type** | DIESEL | **Service documents** | Printout | **Gears** | 7 |
| **Colour** | BLUE | **Number of stamps** | 8 | **Doors** | 5 |
| **VIN** | WVGZZZ5NZKW868380 | **Last service date** | 30/04/2026 | | |

£90 ADDITIONAL FEE
LAST SERVICE 30/04/2026 @ 63,650 MILES (8 SERVICES)

### Tyres

| | | |
|---|---|---|
| **NSF** | BUDGET | 5.0mm |
| **NSR** | BUDGET | 5.0mm |
| **OSF** | BUDGET | 5.0mm |
| **OSR** | BUDGET | 5.0mm |
| **Spare** | | |

## Features

- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking



## Photos




















**Eastbourne Car Auctions**


# Condition Check




## Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm




5: Wing nsf
Chipped
1 To 5



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsf
Chipped
Edge Chip




8: Door nsr
Scratched
Over 25mm Thru Paint




9: Door nsr
Dented
2 Or Less UpTo 10mm



10: Wheel nsr
Scratched
Up To 50mm



11: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



12: Bumper Rear
Scratched
Over 100mm Thru Paint




13: Boot Lid
Dented
Between 10mm + 30mm



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Scratched
Over 25mm Thru Paint



17: Door osf
Dented
Between 10mm + 30mm



18: Door osf
Chipped
Edge Chip



19: Door osf
Chipped
1 To 5



20: Wing osf
Chipped
1 To 5



21: Wheel osf
Scratched
Over 50mm



22: Roof
Scratched
UpTo 25mm Thru Paint

**Interior**

| | | | |
|---|---|---|---|
| **Carpet Condition** | Average | **Upholstery Condition** | Average |
| **Seat Condition** | Average | **Odour** | No |

## Vehicle Inspection Report

**Disclaimer**
**Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.**
**Additional fees may apply to some vendors.**
**Please note buyers rate increase from 01/01/2025**

| | | | |
|---|---|---|---|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Gearbox Static Gear Selection (engine running) | OK |
| Turbo Boosting | OK | No Excessive Smoking | OK |
| Parking Brake | OK | | |

| | | | |
|---|---|---|---|
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |

| | | | |
|---|---|---|---|
| Windows | OK | Radio | OK |
| Sat nav | OK | Steering | OK |