46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

TJ70MOD

Mercedes-Benz GLB GLB 220d 4Matic AMG Line Prem 5dr 8G-Tron [5 seat]

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	01/09/2020	**Body Style**	Estate	**Last service miles**	67,624
Year	2020	**Keys**	2	**MOT Due**	03/08/2027
Mileage	70,016 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
Fuel Type	DIESEL	**Service documents**	Printout	**Gears**	8
Colour	BLACK	**Number of stamps**	6	**Doors**	5
VIN	WDC2476152W012958	**Last service date**	22/07/2026		

£100 ADDITIONAL FEE
LAST SERVICE 22/07/2026 @ 67,624 MILES (6 SERVICES, ALL MAIN DEALER)

Tyres

NSF	RAPID	6.0mm
NSR	PIRELLI	6.0mm
OSF	RAPID	6.0mm
OSR	PIRELLI	6.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim

Photos



















Eastbourne Car Auctions

Condition Check



Damage Photos




1: Wing osf
Chipped
1 To 5



2: Door osr
Chipped
1 To 5



3: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Wheel nsr
Corroded
Light



6: Door nsf
Chipped
Edge Chip



7: Wing nsf
Chipped
1 To 5



8: Bonnet
Chipped
1 To 5



9: Bumper Front
Scratched
UpTo 25mm Thru Paint



10: Boot Lid
Dented
Over 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK