46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

HN67WUU

Skoda Superb 2.0 TDI CR SE L Executive 5dr DSG [7 Speed]

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	07/12/2017
Year	2017
Mileage	145,311 Miles Warranted
Fuel Type	DIESEL
Colour	SILVER
VIN	TMBKH7NP5J7526018

Body Style	Estate
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	7
Last service date	08/09/2026

Last service miles	143,576
MOT Due	06/12/2026
Gearbox	SEMI AUTO
Gears	7
Doors	5

£100 ADDITIONAL FEE
Last Service - 08.09.26 @ 143576 miles (7 services)
Cambelt and water pump replaced 14.11.22 @ 77144 miles

Tyres

NSF	MICHELIN	4.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	4.0mm
OSR	MICHELIN	5.0mm
Spare		


Features

- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Heated front seat
- Telephone
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Radio/CD
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking

Photos


















Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Handle Outer osf
Scratched (Painted)
UpTo 25mm Thru Paint



4: Door osr
Chipped
1 To 5



5: Wheel osr
Scratched
Over 50mm



6: Door osr
Dented
2 Or Less UpTo 10mm




7: Bumper Rear
Scratched
Over 100mm Thru Paint



8: Boot Lid
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Up To 50mm



10: Door nsr
Chipped
1 To 5



11: Wing nsf
Scratched
Over 25mm Thru Paint




12: Wheel nsf
Scratched
Over 50mm



13: Bumper Front
Chipped
Multiple Chips



14: Bonnet
Chipped
1 To 5



15: Screen Front
Chipped
UpTo 10mm



16: Roof
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK