46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

HG12FBN

Honda Jazz 1.4 i-VTEC ES 5dr CVT

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	24/04/2012	**Body Style**	Hatchback	**Last service miles**	117,352
Year	2012	**Keys**	1	**MOT Due**	24/04/2027
Mileage	127,778 Miles Warranted	**Service history**	Yes	**Gearbox**	CVT
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	1
Colour	BLUE	**Number of stamps**	12	**Doors**	5
VIN	SHHGG6860CU017660	**Last service date**	09/04/2024		

Last Service - 09.04.2024 at 117352 miles (12 Services)
Radio screen does not work

Tyres

NSF	NEXEN	5.0mm
NSR	FALKEN	4.0mm
OSF	DAVANTI	4.0mm
OSR	DAVANTI	5.0mm
Spare		

Features

- Rear wiper
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Alloy wheels
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking

Photos











AUTO
ROM/A.SEL
TA
CD/AUX
AM/FM
RPT
SCAN
TITLE
PLAY
A/C










Condition Check




Damage Photos



1: Wing osf
Chipped
1 To 5



2: Wing osf
Dented
2 Or Less UpTo 10mm



3: Door osf
Chipped
1 To 5



4: Door osr
Chipped
1 To 5



5: Wheel osr
Scratched
Up To 50mm




6: Door osr
Chipped
Edge Chip



7: Boot Lid
Dented
With Paint Damage



8: Bumper Rear
Poor Previous Repair
Poor Paint



9: Qtr Panel nsr
Poor Previous Repair
Poor Paint



10: Wheel nsr
Scratched
Up To 50mm



11: Sill ns
Dented
With Paint Damage



12: Door nsf
Chipped
1 To 5



13: Wheel nsf
Scratched
Over 50mm



14: Bumper Front
Chipped
Multiple Chips



15: Bonnet
Chipped
Multiple Chips



16: A Post os
Chipped
1 To 5



17: Door nsr
Dented
With Paint Damage



18: D Post ns
Poor Previous Repair
Poor Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	Fault
		Steering	OK