46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**GF69AVZ**

## Kia Stonic 1.0T GDi 2 5dr

nama GRADE 2

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Margin |
| **V5** | Present |

### Details

| | |
|---|---|
| **Reg. date** | 26/09/2019 |
| **Year** | 2019 |
| **Mileage** | 86,205 Miles Warranted |
| **Fuel Type** | PETROL |
| **Colour** | RED |
| **VIN** | KNAD6811LL6353369 |

| | |
|---|---|
| **Body Style** | Hatchback |
| **Keys** | 2 |
| **Service history** | Yes |
| **Service documents** | Service Book |
| **Number of stamps** | 8 |
| **Last service date** | 12/02/2026 |

| | |
|---|---|
| **Last service miles** | 78,621 |
| **MOT Due** | 25/09/2027 |
| **Gearbox** | MANUAL |
| **Gears** | 6 |
| **Doors** | 5 |

£90 ADDITIONAL FEE
Last Service - 12.02.26 @ 78621 miles (8 services (6 main services))  Only 1 key will start car

### Tyres

| | | |
|---|---|---|
| **NSF** | AVON | 5.0mm |
| **NSR** | AVON | 5.0mm |
| **OSF** | AVON | 5.0mm |
| **OSR** | AVON | 5.0mm |
| **Spare** | | |

## Features

- Bluetooth connection
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking

## Photos





























**Eastbourne Car Auctions**

# Condition Check




## Damage Photos



1: Door osr
Chipped
1 To 5



2: Bumper Rear
Poor Previous Repair
Poor Paint



3: Bumper Rear
Chipped
1 To 5



4: Wheel nsr
Corroded
Light



5: Door nsr
Chipped
1 To 5



6: Door nsf
Chipped
1 To 5



7: Wheel nsf
Corroded
Light




8: Bumper Front
Chipped
Multiple Chips



9: Bonnet
Chipped
1 To 5



10: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



11: Bonnet
Dented
Between 10mm + 30mm

**Interior**

| | | | |
|---|---|---|---|
| **Carpet Condition** | Average | **Upholstery Condition** | Average |
| **Seat Condition** | Average | **Odour** | No |

## Vehicle Inspection Report

**Disclaimer**
**Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.**
**Additional fees may apply to some vendors.**
**Please note buyers rate increase from 01/01/2025**

| | | | |
|---|---|---|---|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |

| | | | |
|---|---|---|---|
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| | | Steering | OK |