46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LS20HSG

Volvo XC90 2.0 B5D [235] Inscription 5dr AWD Geartronic

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	12/06/2020	**Body Style**	Estate	**Last service miles**	57,922
Year	2020	**Keys**	2	**MOT Due**	11/06/2027
Mileage	61,833 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
Fuel Type	ELECTRIC DIESEL	**Service documents**	Printout	**Gears**	8
Colour	GREY	**Number of stamps**	3	**Doors**	5
VIN	YV1LFK2UCL1613326	**Last service date**	02/06/2026		

£90 ADDITIONAL FEE
Last Service - 02.06.26 @ 57922 miles (3 services)

Tyres

NSF	PIRELLI	4.0mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	4.0mm
OSR	PIRELLI	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear electric windows
- Drivers airbag
- Central locking
- Rear headrests
- Passenger airbag
- Remote central locking

Photos








LS20 HSG




10:02
talkSPORT
Connecting phone...
HI
MAX
HI

10:02
talkSPORT
talkSPORT D1 National
UCB 1 D1 National
UCB 2 D1 National
V2 Radio Sussex Sussex
Connecting phone...
HI
MAX
HI

14°c
10:02
0
mph
P




Condition Check



Damage Photos



1: Door osf
Chipped
1 To 5



2: Door osf
Chipped
Edge Chip



3: Door osr
Poor Previous Repair
Paint Flake



4: Bumper Rear
Chipped
1 To 5



5: Bumper Rear
Scratched
Up To 25mm Thru Paint



6: Qtr Panel nsr
Poor Previous Repair
Poor Paint



7: Door nsr
Poor Previous Repair
Poor Paint



8: Door nsf
Chipped
Edge Chip



9: Wheel nsf
Corroded
Light



10: Wing nsf
Chipped
1 To 5



11: Bonnet
Chipped
1 To 5



12: Bumper Front
Chipped
Multiple Chips

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK