46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GX68NFC

BMW 3 Series 320d M Sport 4dr Step Auto

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	30/10/2018
Year	2018
Mileage	89,396 Miles Warranted
Fuel Type	DIESEL
Colour	GREY
VIN	WBA8C520905L49453

Body Style	Saloon
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	6
Last service date	18/05/2026

Last service miles	83,898
MOT Due	Expired
Gearbox	AUTOMATIC
Gears	8
Doors	4

£90 ADDITIONAL FEE
LAST SERVICE 18/05/2026 @ 83,898 MILES (6 SERVICES)
MOT EXPIRED

Tyres

NSF	BRIDGESTONE	3.0mm
NSR	BRIDGESTONE	4.0mm
OSF	BRIDGESTONE	3.0mm
OSR	BRIDGESTONE	4.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

Photos








GX68 NFC





+16.0 °C
117 mi
89396
9396.3
14:14
















Service requirements
Cap XTRA 14:41
Service history
§ vehicle inspection
OK Engine oil
OK Vehicle check
OK Brake fluid
OK Rear brake pads
10/2026


Service history
Cap XTRA 14:41
OK Date: 18.05.2026 Service: 10056 BMW
Mileage: 83.898 mi
OK Date: 16.10.2025 Service: 10056 BMW
Mileage: 78.253 mi
OK Date: 08.10.2024 Service: 10056 BMW
Mileage: 67.134 mi
OK Date: 19.10.2023 Service: 10056 BMW
Mileage: 54.804 mi


Service history
Cap XTRA 14:41
OK Date: 24.04.2023 Service: 10056 BMW
Mileage: 48.367 mi
OK Date: 15.10.2021 Service: 10056 BMW
Mileage: 30.888 mi
OK Date: 31.07.2021 Service: 10056 BMW
Mileage: 28.746 mi
OK Date: 15.07.2020 Service: 10056 BMW


Service history
Cap XTRA 14:41
OK Date: 15.10.2021 Service: 10056 BMW
Mileage: 30.888 mi
OK Date: 31.07.2021 Service: 10056 BMW
Mileage: 28.746 mi
OK Date: 15.07.2020 Service: 10056 BMW
Mileage: 17.115 mi
OK Date: 13.10.2018 Service: 05314 BMW
Mileage: 12 mi

Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
1 To 5



4: Door osr
Dented
Hail - Moderate



5: Door osf
Chipped
Edge Chip




6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Bumper Rear
Scratched
Over 100mm Thru Paint



8: Qtr Panel nsr
Dented
With Paint Damage



9: Wheel nsr
Scratched
Over 50mm



10: Door nsr
Chipped
Multiple Chips



11: Door nsf
Chipped
Multiple Chips



12: Wheel nsf
Scratched
Over 50mm



13: Bumper Front
Chipped
Multiple Chips



14: Bonnet
Chipped
1 To 5



15: A Post os
Chipped
1 To 5



16: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK