46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GF63HHU

Peugeot 308 1.6 HDi 92 Active 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	19/02/2014	**VIN**	VF3LB9HPADS242596	**Gearbox**	MANUAL
Year	2014	**Body Style**	Hatchback	**Gears**	5
Mileage	106,817 Miles Warranted	**Keys**	2	**Doors**	5
		Service history	None		
Fuel Type	DIESEL	**MOT Due**	05/03/2027		
Colour	WHITE				

NO SERVICE HISTORY Clutch pedal has lots of play

Tyres

NSF	BUDGET	3.0mm
NSR	SUNNY	4.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	3.0mm
Spare		

Features

- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Solid Paint
- Traction control
- Cloth seat trim

Photos










16°C
12:49
93.50 MHz
93.50 MHz






Condition Check



Damage Photos



1: Seat Base Cover nsf
Holed
UpTo 3mm



2: Wheel osf
Scratched
Over 50mm



3: Wing osf
Poor Previous Repair
Poor Paint



4: Door osf
Dented
With Paint Damage



5: Sill os
Dented
With Paint Damage



6: Door osr
Chipped
1 To 5



7: Door osr
Chipped
Edge Chip



8: Qtr Panel osr
Chipped
1 To 5



9: Wheel osr
Scratched
Over 50mm



10: Bumper Rear
Poor Previous Repair
Paint Flake



11: Boot Lid
Chipped
1 To 5



12: Qtr Panel nsr
Dented
With Paint Damage



13: Wheel nsr
Scratched
Over 50mm



14: Door nsr
Dented
Over 30mm



15: Door nsf
Chipped
Edge Chip



16: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



17: Wheel nsf
Scratched
Over 50mm



18: Bumper Front
Poor Previous Repair
Paint Flake



19: Bonnet
Chipped
Multiple Chips



20: A Post os
Chipped
1 To 5



21: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK