46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GY71XRZ

Volkswagen T-Cross 1.0 TSI 110 Active 5dr

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	17/12/2021	**Body Style**	Hatchback	**Last service miles**	37,010
Year	2021	**Keys**	2	**MOT Due**	16/12/2026
Mileage	39,945 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Printout	**Gears**	6
Colour	BLUE	**Number of stamps**	5	**Doors**	5
VIN	WVGZZZC1ZNY036830	**Last service date**	10/06/2026		

Last Service - 10.06.26 @ 37010 miles (5 services)

Tyres

NSF	GOODYEAR	Damaged
NSR	PIRELLI	4.0mm
OSF	GOODYEAR	4.0mm
OSR	APOLLO	6.0mm
Spare		


Features

- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos











Gold Radio UK









71 06 00 PL



Condition Check



Damage Photos



1: Door osf
Chipped
Edge Chip



2: Door osr
Chipped
Edge Chip



3: Wheel nsr
Scratched
Over 50mm



4: Door nsf
Chipped
Edge Chip




5: Wing nsf
Chipped
1 To 5



6: Bonnet
Chipped
1 To 5



7: Door nsr
Dented
Between 10mm + 30mm



8: Door nsf
Dented
2 Or Less UpTo 10mm



9: Wing nsf
Dented
Between 10mm + 30mm



10: Tyre nsf
Damaged
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK