46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GL20HUY

Volkswagen Tiguan Allspace 2.0 TDI 4Motion Match 5dr DSG

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	31/07/2020	**Body Style**	Estate	**Last service miles**	79,057
Year	2020	**Keys**	2	**MOT Due**	30/07/2027
Mileage	81,184 Miles Warranted	**Service history**	Yes	**Gearbox**	SEMI AUTO
Fuel Type	DIESEL	**Service documents**	Service Book	**Gears**	7
Colour	GREY	**Number of stamps**	5	**Doors**	5
VIN	WVGZZZ5NZLM136640	**Last service date**	27/07/2026		

£90 ADDITIONAL FEE
LAST SERVICE 27/07/2026 @ 79,057 MILES (5 SERVICES)
WATER PUMP & CAMBELT REPLACED 29/09/2026
Coolant look very dirty

Tyres

NSF	BUDGET	2.0mm
NSR	CONTINENTAL	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	6.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Service indicator
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim


Photos



















Eastbourne Car Auctions

Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint



2: Bonnet
Scratched
UpTo 25mm Thru Paint



3: Wheel nsf
Corroded
Light



4: Bumper Rear
Chipped
1 To 5



5: Wheel osr
Scratched
Over 50mm



6: Door osr
Dented
Between 10mm + 30mm




7: Door osf
Chipped
Edge Chip



8: Wing osf
Chipped
1 To 5



9: Wheel osf
Scratched
Over 50mm



10: Roof
Dented
Over 30mm



11: Door nsr
Poor Previous Repair
Rippled UpTo 30%

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK