46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GU17GVN

Audi A3 1.4 TFSI S Line 4dr S Tronic

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	06/03/2017	**Body Style**	Saloon	**Last service miles**	24,830
Year	2017	**Keys**	2	**MOT Due**	05/03/2027
Mileage	47,401 Miles Warranted	**Service history**	Yes	**Gearbox**	SEMI AUTO
Fuel Type	PETROL	**Service documents**	Printout	**Gears**	7
Colour	GREY	**Number of stamps**	3	**Doors**	4
VIN	WAUZZZ8V8H1056160	**Last service date**	23/02/2023		

£90 ADDITIONAL FEE
Last Service - 23.02.23 @ 24830 miles (3 services)

Tyres

NSF	HIFLY	Damaged
NSR	HIFLY	Damaged
OSF	HIFLY	Damaged
OSR	HIFLY	5.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Service indicator
- Electric door mirrors
- Front electric windows
- Rear headrests
- ABS
- Passenger airbag
- Partial leather seat trim
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- PAS
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking


Photos

























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Tyre osf
Damaged
Replace



2: Tyre nsf
Damaged
Replace



3: Tyre nsr
Damaged
Replace



4: Bonnet
Chipped
1 To 5




5: Bumper Front
Chipped
1 To 5



6: Wing nsf
Dented
Between 10mm + 30mm



7: Wheel nsf
Scratched
Over 50mm



8: Door nsf
Chipped
Edge Chip



9: Door nsr
Chipped
1 To 5



10: B Post ns
Scratched
UpTo 25mm Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Qtr Panel nsr
Dented
Between 10mm + 30mm



13: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



14: Bumper Rear
Scratched
25 to 100mm Thru Paint



15: Wheel osr
Scratched
Over 50mm



16: Sill Panel Trim os
Scratched (Painted)
Over 25mm Thru Paint



17: Door osf
Chipped
Edge Chip



18: Wing osf
Scratched
UpTo 25mm Thru Paint



19: Wheel osf
Scratched
Over 50mm



20: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK