46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LO70LSE

Volkswagen Tiguan 1.5 TSI 150 R-Line 5dr DSG

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	08/01/2021	**Body Style**	Estate	**Last service miles**	27,444
Year	2021	**Keys**	2	**MOT Due**	07/01/2027
Mileage	59,614 Miles Warranted	**Service history**	Yes	**Gearbox**	SEMI AUTO
Fuel Type	PETROL	**Service documents**	Printout	**Gears**	7
Colour	BLUE	**Number of stamps**	3	**Doors**	5
VIN	WVGZZZ5NZMW038781	**Last service date**	22/12/2023		

£90 ADDITIONAL FEE
Last Service - 22.12.23 @ 27444 miles (3 services)

Tyres

NSF	FARROAD	5.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	Damaged
OSR	BUDGET	Damaged
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos








LO70 LSE






751



8:15
15.0°C
Please switch on light.
P
0
mph





8:15
BBC Radio2
OFF
OFF







Condition Check



Damage Photos



1: Door osf
Chipped
Edge Chip



2: Door osr
Chipped
1 To 5



3: Door osr
Chipped
Edge Chip



4: Qtr Panel osr
Chipped
1 To 5



5: Bumper Rear
Chipped
1 To 5



6: Boot Lid
Scratched
UpTo 25mm Thru Paint



7: Door nsr
Chipped
1 To 5



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Wing nsf
Chipped
1 To 5



10: Bumper Front
Scratched
UpTo 25mm Thru Paint



11: Tyre osf
Damaged
Replace



12: Tyre osr
Damaged
Replace



13: Qtr Panel nsr
Dented
Between 10mm + 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK