46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GD68UZX

Nissan Qashqai 1.3 DiG-T Tekna 5dr

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	19/01/2019	**Keys**	1	**CAP Clean**	£6,750.00
Year	2019	**Service history**	Yes	**CAP Average**	£5,900.00
Mileage	60,929 Miles Warranted	**Service documents**	Service Book	**CAP Below**	£5,050.00
Fuel Type	PETROL	**Number of stamps**	7	**Gearbox**	MANUAL
Colour	BLACK	**Last service date**	03/04/2026	**Gears**	6
VIN	SJNFFAJ11U2485179	**Last service miles**	58,802	**Doors**	5
Body Style	Hatchback	**MOT Due**	30/03/2027		

Last Service - 03.04.26 @ 58802 miles (7 services)

Tyres

NSF	NEXEN	5.0mm
NSR	BUDGET	5.0mm
OSF	NEXEN	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking




Photos









GD68 UZX



11:51
13°c
149
60929



FM
11:51
Source
FM Menu
102.4 MHz
Heart
Pop Music
AUDIO
BACK
OK
A/C
AUTO
ON-OFF

FM
Heart
11:51
AUDIO
BACK
OK
A/C
AUTO
ON-OFF

Ensure it is safe before manoeuvring.
AUDIO
BACK
OK
A/C

Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front Moulding
Scratched (Painted)
UpTo 25mm Thru Paint



4: Fogdriving Lamp osf
Broken
Replace



5: Wing nsf
Dented
2 Or Less UpTo 10mm



6: Wing nsf
Chipped
1 To 5




7: Wheel nsf
Scratched
Over 50mm



8: Bumper Front
Scratched
25 to 100mm Thru Paint



9: Wing Front Arch Extension ns
Scuffed (Unpainted)
UpTo 100mm



10: Door nsf
Scratched
UpTo 25mm Thru Paint



11: Door nsr
Chipped
Edge Chip



12: Wheel nsr
Scratched
Over 50mm



13: Qtr Panel nsr
Chipped
1 To 5



14: Bumper Rear
Chipped
1 To 5



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Scratched
Over 25mm Thru Paint



17: Qtr Panel Trim os
Scuffed
Over 25mm



18: Door osf
Chipped
Edge Chip



19: Wing osf
Scratched
UpTo 25mm Thru Paint



20: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK