46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GV18GHB

Mini Hatchback 1.5 Cooper II 5dr

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	15/06/2018	**VIN**	WMWXU72030TE35702	**Gearbox**	MANUAL
Year	2018	**Body Style**	Hatchback	**Gears**	6
Mileage	92,777 Miles Warranted	**Keys**	2	**Doors**	5
		Service history	None		
Fuel Type	PETROL	**MOT Due**	14/06/2027		
Colour	BLUE				

No Service History

Tyres

NSF	HABILEAD	5.0mm
NSR	SUNNY	5.0mm
OSF	HABILEAD	5.0mm
OSR	SUNNY	5.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Service indicator
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- PAS
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos












KISSTORY 9:32
MEDIA/RADIO
POP
KISSTORY
MODE



MODE


MINI


SERVICE REQUIREMENTS
KISSTORY 9:32
Service history
09/2027
OK Vehicle inspection
OK Emission inspection
OK Brake fluid
OK Engine oil
OK Vehicle check



SERVICE HISTORY
KISSTORY 9:32
Date: 19.03.2018
Service: 08637 MINI







Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Chipped
1 To 5



3: Bumper Front Grill
Broken
Replace



4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm




7: Wing nsf
Scratched
Over 25mm Thru Paint




8: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



9: Door nsf
Dented
Between 10mm + 30mm



10: Door nsf
Scratched
Over 25mm Thru Paint



11: Door nsr
Poor Previous Repair
Rippled UpTo 30%



12: Wheel nsr
Scratched
Over 50mm




13: Qtr Panel nsr
Dented
With Paint Damage



14: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



15: Bumper Rear
Scratched
Over 100mm Thru Paint




16: Qtr Panel osr
Scratched
Over 25mm Thru Paint



17: Wheel osr
Scratched
Over 50mm



18: Door osr
Dented
Over 30mm



19: Door osr
Scratched
Over 25mm Thru Paint



20: Door osf
Scratched
Over 25mm Thru Paint



21: Door osr
Dented
2 Or Less UpTo 10mm




22: Wheel osf
Scratched
Over 50mm



23: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



24: Screen Front
Chipped
Over 10mm



25: Roof
Chipped
Edge Chip

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK