46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

WK14XJL

Honda Civic 1.4 i-VTEC S 5dr

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	12/05/2014
Year	2014
Mileage	80,531 Miles Warranted
Fuel Type	PETROL
Colour	RED
VIN	SHHFK1740EU000565

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	5
Last service date	24/09/2024

Last service miles	67,024
MOT Due	26/11/2026
Gearbox	MANUAL
Gears	6
Doors	5

£90 ADDITIONAL FEE
Last Service - 24.09.2024 at 67024 miles (5 Services)

Tyres

NSF	RAPID	5.0mm
NSR	GRENLANDER	4.0mm
OSF	RAPID	5.0mm
OSR	GRENLANDER	4.0mm
Spare		

Features

- PAS
- Radio/CD
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Service indicator
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim

Photos







MK14 KJL




FM/AM
TA
CD
AUX
VOL
PUSH
SELECT
SETUP
SCAN
22
AUTO




FM1
BBC R1
0 25 50 75 100
AVG
39.7 mpg
14°c
080531 miles
12:48










Condition Check



Damage Photos



1: Seat Back Cover osf
Scuffed
Over 25mm



2: Door Pad osr
Soiled
Heavy



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front
Poor Previous Repair
Paint Flake



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Wing nsf
Scratched
Over 25mm Thru Paint




8: A Post os
Dented
Between 10mm + 30mm



9: Roof
Dented
Over 30mm



10: B Post ns
Scratched
Over 25mm Thru Paint



11: Door nsf
Poor Previous Repair
Rippled UpTo 30%



12: Door nsr
Dented
With Paint Damage



13: Wheel nsr
Scratched
Over 50mm



14: Aperture Seal nsr
Broken
Replace



15: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



16: Bumper Rear
Scratched
Over 100mm Thru Paint



17: Boot Lid
Poor Previous Repair
Poor Paint



18: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint




19: Wheel osr
Scratched
Over 50mm



20: Door osr
Dented
With Paint Damage



21: Aperture Seal osr
Broken
Replace



22: B Post os
Dented
Between 10mm + 30mm



23: Door osf
Poor Previous Repair
Rippled UpTo 30%



24: Other
N/A
N/A
Trim on the door broken



25: A Post os
Chipped
1 To 5



26: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



27: Wheel osf
Scratched
Over 50mm



28: Wing osf
Chipped
1 To 5



29: Bonnet
Dented
Between 10mm + 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK