46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LS60VTW

Mercedes-Benz C Class C220 CDI BlueEFFICIENCY Sport 5dr Auto

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	20/01/2011
Year	2011
Mileage	127,846 Miles Warranted
Fuel Type	DIESEL
Colour	SILVER
VIN	WDD2042022F629562

Body Style	Estate
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	14
Last service date	29/10/2024

Last service miles	111,268
MOT Due	15/09/2027
Gearbox	AUTOMATIC
Gears	5
Doors	5

£90 ADDITIONAL FEE
MOT MILEAGE DISCREPANCY 30/11/2018 & 24/01/2017
LAST SERVICE 29/10/2024 @ 111,268 MILES (14 SERVICES) Service overdue

Tyres

NSF	ZEETEX	Damaged
NSR	BUDGET	5.0mm
OSF	ZEETEX	Damaged
OSR	BUDGET	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Radio/CD
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Park assist camera
- Service indicator
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Digital radio
- Electric sunroof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos
































Eastbourne Car Auctions

Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm



2: Bonnet
Chipped
1 To 5



3: Screen Front
Cracked
Replace



4: Bumper Front
Dented
With Paint Damage



5: Wing nsf
Poor Previous Repair
Poor Paint



6: Bumper Front
Insecure
Action Required



7: Wheel nsf
Scratched
Over 50mm



8: A Post ns
Scratched
UpTo 25mm Thru Paint



9: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



10: Door nsf
Poor Previous Repair
Poor Paint



11: Door nsr
Poor Previous Repair
Poor Paint



12: Wheel nsr
Scratched
Over 50mm



13: Qtr Panel nsr
Dented
With Paint Damage



14: Bumper Rear
Cracked
Over 25mm



15: Qtr Panel osr
Dented
With Paint Damage



16: Wheel osr
Scratched
Over 50mm



17: Door osr
Dented
With Paint Damage



18: Door osf
Dented
With Paint Damage



19: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



20: Wing osf
Scratched
UpTo 25mm Thru Paint



21: Wheel osf
Scratched
Over 50mm



22: Door Pad osf
Scuffed
Over 25mm



23: Tyre osf
Damaged
Replace



24: Tyre nsf
Damaged
Replace



25: Rear TowEye Cvr
Missing
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		