46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

HJ55NVA

Honda CR-V 2.0 i-VTEC Executive 5dr Auto

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	01/09/2005	**Body Style**	Estate	**Last service miles**	61,483
Year	2005	**Keys**	2	**MOT Due**	27/07/2027
Mileage	140,250 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	4
Colour	SILVER	**Number of stamps**	6	**Doors**	5
VIN	SHSRD88905U325192	**Last service date**	12/01/2015		

Last Service -12.01.2015 at 61483 miles (6 Services) Engine knocking
Boot will not open
Faulty ns mirror

Tyres

NSF	RAPID	6.0mm
NSR	HANKOOK	5.0mm
OSF	RAPID	6.0mm
OSR	HANKOOK	5.0mm
Spare		

Features

- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Central locking
- Heated front seat
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Remote central locking
- Navigation system
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Leather seat trim
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Alloy wheels

Photos




















Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Poor Previous Repair
Poor Paint



3: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



4: Door osf
Scratched
UpTo 25mm Thru Paint



5: Door osf
Dented
Between 10mm + 30mm



6: Door osr
Chipped
1 To 5



7: Wheel osr
Scratched
Over 50mm



8: Qtr Panel osr
Chipped
1 To 5



9: Bumper Rear
Poor Previous Repair
Poor Paint



10: Qtr Panel nsr
Dented
With Paint Damage



11: Wheel nsr
Scratched
Over 50mm



12: Door nsr
Chipped
1 To 5



13: Door nsf
Chipped
Edge Chip



14: Wing nsf
Scratched
UpTo 25mm Thru Paint



15: Wheel nsf
Scratched
Over 50mm



16: Bumper Front
Scratched
Over 100mm Thru Paint



17: Bonnet
Chipped
1 To 5



18: Roof
Poor Previous Repair
Paint Flake



19: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		