46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

ND70OVR

Audi E-Tron 230kW 50 Quattro 71kWh Technik 5dr Auto

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	31/12/2020	**Body Style**	Estate	**Last service miles**	54,093
Year	2020	**Keys**	2	**MOT Due**	27/03/2027
Mileage	59,290 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
Fuel Type	Electric	**Service documents**	Printout	**Gears**	1
Colour	BLACK	**Number of stamps**	3	**Doors**	5
VIN	WAUZZZGE1MB020946	**Last service date**	15/01/2025		

£90 ADDITIONAL FEE
LAST SERVICE 15/01/2025 @ 54,093 MILES (3 SERVICES) Bird dropping stains on most panels
No charging cables

Tyres

NSF	CONTINENTAL	4.0mm
NSR	CONTINENTAL	4.0mm
OSF	CONTINENTAL	Damaged
OSR	CONTINENTAL	4.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear electric windows
- Drivers airbag
- Central locking
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Bumper Rear
Scratched
25 to 100mm Thru Paint



2: Wheel nsr
Scratched
Over 50mm



3: Door nsr
Scratched
UpTo 25mm Thru Paint



4: Door nsf
Chipped
1 To 5



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Wing nsf
Chipped
1 To 5



7: Bumper Front
Scratched
25 to 100mm Thru Paint



8: Tyre osf
Damaged
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK