46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

AV70XDY

Audi A4 35 TFSI Black Edition 5dr S Tronic

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	26/01/2021	**Body Style**	Estate	**Last service miles**	3,719
Year	2021	**Keys**	2	**MOT Due**	04/12/2026
Mileage	31,435 Miles Warranted	**Service history**	Yes	**Gearbox**	SEMI AUTO
Fuel Type	PETROL	**Service documents**	Printout	**Gears**	7
Colour	RED	**Number of stamps**	2	**Doors**	5
VIN	WAUZZZF41MA035901	**Last service date**	06/11/2023		

£90 ADDITIONAL FEE
Last Service - 06.11.23 @ 3719 miles (2 main dealer services)

Tyres

NSF	HANKOOK	Damaged
NSR	HANKOOK	5.0mm
OSF	HANKOOK	4.0mm
OSR	HANKOOK	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Park assist camera
- Service indicator
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Partial leather seat trim
- Heated front seat
- Rear parking sensor
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels

Photos




















Eastbourne Car Auctions

Condition Check



Damage Photos




1: Tyre nsf
Damaged
Replace



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Chipped
1 To 5



7: Door nsf
Chipped
Edge Chip



8: Door nsr
Dented
Over 30mm



9: Wheel nsr
Scratched
Over 50mm



10: Wheel osr
Corroded
Light



11: Door osr
Chipped
Edge Chip



12: Door osf
Chipped
Edge Chip



13: Wing osf
Chipped
1 To 5



14: Wheel osf
Scratched
Over 50mm



15: A Post os
Scratched
Over 25mm Thru Paint



16: Roof
Chipped
Edge Chip

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK