46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

SD73WPE

Peugeot 2008 1.2 PureTech 130 Allure 5dr

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	VAT Qualifying
V5	Photocopy

Details

Reg. date	25/10/2023	**Keys**	1	**CAP Clean**	£10,150.00
Year	2023	**Service history**	Yes	**CAP Average**	£9,025.00
Mileage	43,704 Miles Warranted	**Service documents**	Service Book	**CAP Below**	£7,850.00
Fuel Type	PETROL	**Number of stamps**	1	**Gearbox**	MANUAL
Colour	GREY	**Last service date**	07/11/2024	**Gears**	6
VIN	VR3USHNSKPJ836096	**Last service miles**	13,356	**Doors**	5
Body Style	Hatchback	**MOT Due**	Expired		

Last Service - 07.11.24 @ 13356 miles (1 service)
V5 photocopy only

Tyres

NSF	GOODYEAR	5.0mm
NSR	GOODYEAR	5.0mm
OSF	GOODYEAR	5.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features

- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Front parking sensor
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim


Photos
























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door osf
Chipped
1 To 5




3: Door osf
Chipped
Edge Chip



4: Bumper Rear
Chipped
Multiple Chips



5: Door nsf
Chipped
Edge Chip




6: Door Mirror Assy nsf
Missing
Replace



7: Bumper Front
Chipped
1 To 5



8: Bonnet
Chipped
1 To 5



9: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK