46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GF66LMM

Nissan Qashqai 1.2 DiG-T N-Connecta 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	31/10/2016
Year	2016
Mileage	81,039 Miles Warranted
Fuel Type	PETROL
Colour	BLUE
VIN	SJNFEAJ11U1848914

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	5
Last service date	11/02/2023

Last service miles	56,416
MOT Due	Expired
Gearbox	MANUAL
Gears	6
Doors	5

£100 ADDITIONAL FEE
Last Service - 11.02.23 at 56416 miles (5 services) Engine noisy when revved
EML light is on car has been plugged in and detects fuel pressure regulator control circuit

Tyres

NSF	YOKOHAMA	3.0mm
NSR	YOKOHAMA	4.0mm
OSF	AVON	5.0mm
OSR	CONTINENTAL	3.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking


Photos





























Eastbourne Car Auctions

Condition Check



Damage Photos




1: Wheel nsf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Door osf
Chipped
1 To 5



5: Door osr
Scratched
Over 25mm Thru Paint




6: Qtr Panel osr
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
Over 30mm




8: Door nsr
Dented
With Paint Damage



9: Door nsf
Scratched
Over 25mm Thru Paint



10: Bumper Front
Chipped
Multiple Chips




11: Bonnet
Chipped
Multiple Chips



12: Screen Front
Chipped
UpTo 10mm



13: Other
N/A
N/A



14: Door nsf
Dented
Between 10mm + 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		