46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GV71MWC

Vauxhall Astra 1.2 Turbo 145 Griffin Edition 5dr

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	24/12/2021	**Keys**	2	**CAP Clean**	£5,975.00
Year	2021	**Service history**	Yes	**CAP Average**	£5,225.00
Mileage	55,255 Miles Warranted	**Service documents**	Service Book	**CAP Below**	£4,450.00
Fuel Type	PETROL	**Number of stamps**	4	**Gearbox**	MANUAL
Colour	BLACK	**Last service date**	03/12/2025	**Gears**	6
VIN	W0VBE6EW7NG032748	**Last service miles**	44,790	**Doors**	5
Body Style	Hatchback	**MOT Due**	23/12/2026		

LAST SERVICE 03/12/2025 @ 44,790 MILES (4 SERVICES, ALL MAIN DEALER)

Tyres

NSF	CONTINENTAL	4.0mm
NSR	HANKOOK	4.0mm
OSF	HANKOOK	4.0mm
OSR	NEXEN	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Heated front seat
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels

Photos










EY71 MNC




Check
Number Plate
Lamp

101.5
FM






Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Dented
Between 10mm + 30mm



3: Door Mirror Assy osf
Missing
Replace



4: Door osf
Chipped
Edge Chip



5: Door osr
Scratched
UpTo 25mm Thru Paint



6: Door osr
Chipped
1 To 5



7: Wheel osr
Scratched
Over 50mm



8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Cracked
Over 25mm




10: Qtr Panel nsr
Dented
With Paint Damage



11: Wheel nsr
Scratched
Over 50mm



12: Door nsr
Dented
With Paint Damage



13: Door nsf
Dented
With Paint Damage



14: Sill ns
Scratched
UpTo 25mm Thru Paint



15: Wheel nsf
Scratched
Over 50mm



16: Wing nsf
Chipped
Multiple Chips



17: Bumper Front
Scratched
Over 100mm Thru Paint



18: Bonnet
Chipped
1 To 5



19: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK