46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GU64PFY

Kia Soul 1.6 CRDi Shaker 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	30/09/2014	**Body Style**	Hatchback	**Last service miles**	59,547
Year	2014	**Keys**	2	**MOT Due**	Expired
Mileage	60,268 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	DIESEL	**Service documents**	Service Book	**Gears**	6
Colour	BLACK	**Number of stamps**	11	**Doors**	5
VIN	KNAJT813LD7613538	**Last service date**	30/09/2025		

Last Service - 30.09.2025 at 59547 miles (11 Services)
Clutch Replaced 11.04.2025 @ 58878 Miles Low clutch

Tyres

NSF	AVON	4.0mm
NSR	RAPID	3.0mm
OSF	AVON	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features

- Bluetooth connection
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking
- Telephone
- Electric sunroof
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Radio/CD
- Air conditioning
- Metallic Paint
- Traction control
- Alloy wheels

Photos


















LO64 PFY





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Chipped
1 To 5



3: Door osf
Dented
With Paint Damage




4: Door osr
Dented
With Paint Damage



5: Qtr Panel osr
Dented
With Paint Damage



6: Wheel osr
Corroded
Light



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Boot Lid
Chipped
1 To 5




9: Qtr Panel nsr
Chipped
1 To 5



10: Wheel nsr
Corroded
Light




11: Door nsr
Chipped
Edge Chip



12: Door nsr
Chipped
1 To 5



13: Door nsf
Chipped
Edge Chip



14: Door nsf
Chipped
1 To 5



15: Wheel nsf
Corroded
Light




16: Wing nsf
Chipped
1 To 5



17: Bonnet
Chipped
Multiple Chips



18: Bumper Front
Chipped
Multiple Chips



19: Screen Front
Chipped
UpTo 10mm



20: A Post os
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK