46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

CV18GZJ

Vauxhall Astra 1.0T ecoTEC Tech Line Nav 5dr

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	04/06/2018	**Body Style**	Hatchback	**Last service miles**	120,719
Year	2018	**Keys**	1	**MOT Due**	30/03/2027
Mileage	127,860 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	5
Colour	WHITE	**Number of stamps**	5	**Doors**	5
VIN	W0VBD6EA1JG099394	**Last service date**	31/03/2026		

Last Service - 31.03.2026 at 120719 miles (5 Services) Intermittent EML
Both corners of front bumper badly painted
NSF headlight scratched

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Service indicator
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking


Photos






CV18 CZJ










Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Paint Flake



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Dented
Over 30mm



5: A Post ns
Dented
With Paint Damage



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



7: Door nsf
Chipped
1 To 5



8: Door nsf
Dented
Between 10mm + 30mm



9: Qtr Panel nsr
Dented
With Paint Damage



10: Wheel nsr
Scratched
Up To 50mm



11: Bumper Rear
Poor Previous Repair
Paint Flake



12: Qtr Panel osr
Poor Previous Repair
Poor Paint



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Poor Previous Repair
Poor Paint



15: Door osf
Dented
Over 30mm



16: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



17: Wing osf
Chipped
Multiple Chips



18: Wheel osf
Scratched
Over 50mm



19: Roof
Poor Previous Repair
Paint Flake



20: Screen Front
Chipped
Over 10mm



21: Other
N/A
N/A
Scratched



22: Boot Lid
Chipped
1 To 5



23: Other
N/A
N/A
Osf headlight scratched and chipped



24: Screen Rear
Scratched
Over 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK