46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

NA15NKH

Nissan Qashqai 1.5 dCi N-Tec+ 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	19/05/2015
Year	2015
Mileage	103,897 Miles Warranted
Fuel Type	DIESEL
Colour	GREY
VIN	SJNFAAJ11U1394432
Body Style	Hatchback

Keys	1
Service history	Yes
Service documents	Service Book
Number of stamps	5
Last service date	05/05/2022
Last service miles	55,020
MOT Due	03/08/2027

CAP Clean	£2,600.00
CAP Average	£2,150.00
CAP Below	£1,700.00
Gearbox	MANUAL
Gears	6
Doors	5

Last Service - 05.05.2022 at 55020 miles (5 Services)

Tyres

NSF	SUNNY	4.0mm
NSR	AVON	2.0mm
OSF	SUNNY	4.0mm
OSR	WESTLAKE	5.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Digital radio
- Fixed panoramic glass roof
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Radio/CD
- Front fog lights
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Navigation system
- Rear wiper
- Body coloured bumpers
- Roof rails
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos









NA15 NKH





16:16
15°C
103897 mm

7-12
DAB List
TA
Extra chan.
ENTER
Lo
A/C
Lo
AUTO
ON-OFF
DUAL
PASSENGER AIR BAG

talkSPORT
16:16
MAP
NAV
INFO
SETUP
BACK
ENTER
Menu
Lo
A/C
Lo
ON-OFF

MAP
NAV
INFO
SETUP
BACK
ENTER
Ensure it is safe before manoeuvring.
Lo

Condition Check



Damage Photos



1: Fascia Trim
Missing
Replace



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Chipped
Multiple Chips



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Dented
With Paint Damage



6: Door Mirror Assy nsf
Broken
Replace



7: Door nsr
Dented
With Paint Damage




8: Door Moulding nsr
Scuffed (Unpainted)
Over 100mm



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Wheel osr
Corroded
Light




13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Door osr
Dented
Between 10mm + 30mm
Multiple dents



15: Door osr
Scratched
Over 25mm Thru Paint



16: Door osf
Dented
With Paint Damage



17: Wheel osf
Scratched
Over 50mm



18: Wing osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK