46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

KY16DDL

Seat Ibiza 1.2 TSI 90 Connect 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	01/03/2016
Year	2016
Mileage	112,992 Miles Warranted
Fuel Type	PETROL
Colour	GREY
VIN	VSSZZZ6JZGR030589

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	4
Last service date	12/03/2025

Last service miles	98,737
MOT Due	05/03/2027
Gearbox	MANUAL
Gears	5
Doors	5

£100 ADDITIONAL FEE
Last Service - 12.03.25 @ 98737 miles (4 services)

Tyres

NSF	FALKEN	5.0mm
NSR	FALKEN	5.0mm
OSF	FALKEN	5.0mm
OSR	FALKEN	5.0mm
Spare		

Features

- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Navigation system
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Metallic Paint
- Traction control
- Cloth seat trim
- Telephone
- Air conditioning
- ABS
- Tyre pressure monitor
- Leather seat trim

Photos


























Eastbourne Car Auctions

Condition Check



Damage Photos




1: Wheel osf
Corroded
Light



2: Wing osf
Poor Previous Repair
Poor Paint



3: Door osf
Chipped
Edge Chip



4: Door osf
Chipped
1 To 5



5: Door osr
Chipped
1 To 5



6: Door osr
Chipped
Edge Chip



7: Wheel osr
Corroded
Light



8: Qtr Panel osr
Chipped
1 To 5



9: Bumper Rear
Chipped
1 To 5



10: Qtr Panel nsr
Dented
With Paint Damage



11: Wheel nsr
Corroded
Light




12: Door nsr
Scratched
Over 25mm Thru Paint



13: Door nsf
Dented
With Paint Damage



14: A Post ns
Dented
With Paint Damage



15: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



16: Wheel nsf
Corroded
Light




17: Wing nsf
Poor Previous Repair
Poor Paint



18: Bumper Front
Poor Previous Repair
Poor Paint



19: Bonnet
Poor Previous Repair
Poor Paint



20: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Poor	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK