46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**GM15WZG**

## Kia Rio 1.25 SR7 5dr

nama GRADE 5

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Margin |
| **V5** | Present |

### Details

| | |
|---|---|
| **Reg. date** | 18/07/2015 |
| **Year** | 2015 |
| **Mileage** | 54,805 Miles Warranted |
| **Fuel Type** | PETROL |
| **Colour** | RED |
| **VIN** | KNADN511LF6513072 |

| | |
|---|---|
| **Body Style** | Hatchback |
| **Keys** | 2 |
| **Service history** | Yes |
| **Service documents** | Printout |
| **Number of stamps** | 5 |
| **Last service date** | 13/05/2026 |

| | |
|---|---|
| **Last service miles** | 53,442 |
| **MOT Due** | 14/06/2027 |
| **Gearbox** | MANUAL |
| **Gears** | 5 |
| **Doors** | 5 |

£100 ADDITIONAL FEE
Last Service - 13.05.26 @ 53442 miles (5 services)

### Tyres

| | | |
|---|---|---|
| **NSF** | BUDGET | 4.0mm |
| **NSR** | TRIANGLE | 4.0mm |
| **OSF** | BUDGET | 3.0mm |
| **OSR** | TRIANGLE | 4.0mm |
| **Spare** | | |

## Features

- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

## Photos














GM15 WZG





# Condition Check




## Damage Photos



1: Carpets Front
Holed
Over 3mm



2: Wheel osf
Scratched
Up To 50mm



3: Wing osf
Chipped
1 To 5




4: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



5: Door osf
Chipped
1 To 5



6: Door osr
Dented
With Paint Damage



7: Qtr Panel osr
Dented
With Paint Damage



8: Handle Outer osf
Scratched (Painted)
Over 25mm Thru Paint



9: Wheel osr
Scratched
Up To 50mm



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Qtr Panel nsr
Dented
With Paint Damage



12: Door nsr
Dented
With Paint Damage



13: Door nsf
Dented
With Paint Damage



14: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



15: Wing nsf
Scratched
Over 25mm Thru Paint



16: Bumper Front
Scratched
Over 100mm Thru Paint

**Interior**

| | | | |
|---|---|---|---|
| **Carpet Condition** | Average | **Upholstery Condition** | Average |
| **Seat Condition** | Average | **Odour** | No |

## Vehicle Inspection Report

**Disclaimer**
**Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.**
**Additional fees may apply to some vendors.**
**Please note buyers rate increase from 01/01/2025**

| | | | |
|---|---|---|---|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| | | Steering | OK |