46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GU65FFX

Subaru Outback 2.5i SE Premium 5dr Lineartronic

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	20/11/2015	**Body Style**	Estate	**Last service miles**	118,893
Year	2015	**Keys**	2	**MOT Due**	18/09/2027
Mileage	154,733 Miles Warranted	**Service history**	Yes	**Gearbox**	CVT
Fuel Type	PETROL	**Service documents**	Printout	**Gears**	6
Colour	BLUE	**Number of stamps**	9	**Doors**	5
VIN	JF1BS9KC2FG008519	**Last service date**	17/09/2024		

£100 ADDITIONAL FEE
Last Service - 17.09.24 @ 118893 miles (9 services) Electric tailgate need attention

Tyres

NSF	FALKEN	6.0mm
NSR	BUDGET	4.0mm
OSF	FALKEN	6.0mm
OSR	BUDGET	4.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Digital radio
- Front fog lights
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Body coloured bumpers
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Electric sunroof
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim

Photos










GU66 FFX


GU66 FFX
OUTBACK




Edgeland Terrace
Mallard Close
Brampton Road
Broadwater Way
Menu
INFO
HOME
MAP
APPS
MODE
A/C
OFF


HOME
MAP
AUDIO
TELEPHONE
APPS
INFO
SETTINGS
INFO
HOME
MAP
APPS
MODE
A/C
OFF


Check Surroundings Before Backing Up
INFO
HOME
MAP
APPS
MODE
A/C
OFF




Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Poor Previous Repair
Paint Flake




3: Grille Front
Broken
Replace



4: Bumper Front
Insecure
Action Required



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Scratched
Over 25mm Thru Paint



7: A Post ns
Chipped
1 To 5



8: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



9: Door nsf
Dented
With Paint Damage



10: Door nsr
Dented
With Paint Damage



11: Wheel nsr
Scratched
Over 50mm



12: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




13: Bumper Rear
Dented
With Paint Damage



14: Boot Lid
Scratched
UpTo 25mm Thru Paint



15: Wheel osr
Scratched
Up To 50mm



16: Door osr
Dented
Between 10mm + 30mm



17: Door osr
Scratched
UpTo 25mm Thru Paint



18: Door osf
Scratched
Over 25mm Thru Paint



19: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		