46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

WU21YLF

Toyota Prius 1.8 VVTi Business Edition Plus 5dr CVT AWD

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	26/03/2021	**Body Style**	Hatchback	**Last service miles**	55,166
Year	2021	**Keys**	2	**MOT Due**	05/01/2027
Mileage	67,800 Miles Warranted	**Service history**	Yes	**Gearbox**	CVT
Fuel Type	HYBRID ELECTRIC	**Service documents**	Service Book	**Gears**	1
Colour	GREY	**Number of stamps**	4	**Doors**	5
VIN	JTDL93FU503028096	**Last service date**	23/12/2025		

£100 ADDITIONAL FEE
Last Service - 23.12.25 @ 55166 miles (4 services)

Tyres

NSF	BRIDGESTONE	6.0mm
NSR	BRIDGESTONE	6.0mm
OSF	BRIDGESTONE	6.0mm
OSR	BRIDGESTONE	6.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Steel wheels
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos






























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door osf
Chipped
Edge Chip



3: Door nsr
Chipped
1 To 5



4: Bumper Front
Chipped
1 To 5



5: Bonnet
Chipped
1 To 5



6: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door osf
Scratched
Over 25mm Thru Paint



8: Door osr
Dented
With Paint Damage




9: Qtr Panel osr
Chipped
1 To 5



10: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



11: Door nsr
Dented
Between 10mm + 30mm



12: Door nsf
Scratched
UpTo 25mm Thru Paint



13: Wing nsf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK