46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

RK67KXO

Dacia Duster 1.2 TCe 125 Prestige 5dr

nama GRADE 5

Inspection		Vehicle	
Serious Damage?	No	**VAT**	Margin
		V5	Present

Details

Reg. date	01/09/2017	**Body Style**	Hatchback	**Last service miles**	70,192
Year	2017	**Keys**	2	**MOT Due**	10/01/2027
Mileage	76,078 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	6
Colour	BLUE	**Number of stamps**	7	**Doors**	5
VIN	UU1HSDCW658478762	**Last service date**	23/12/2025		

LAST SERVICE 23/12/2025 @ 70,192 MILES (7 SERVICES) Exhaust loose and rattling
Car locks it's self
Intermittent misfire

Tyres

NSF	BUDGET	5.0mm
NSR	CONTINENTAL	4.0mm
OSF	BUDGET	3.0mm
OSR	CONTINENTAL	4.0mm
Spare		

Features




- Bluetooth connection
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim

Photos









160 78

Brampton Road
Eastbourne
09:56
Options
OK

FM
09:56
BBC1 Londn
BBC R2
BBC R3
BBC R4
Classic
Smooth
Main
List
Presets
Options

DUSTER
BLUE
DACIA




Condition Check



Damage Photos



1: Wing osf
Scratched
UpTo 25mm Thru Paint



2: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



3: Door osf
Scratched
Over 25mm Thru Paint



4: Qtr Panel osr
Chipped
1 To 5



5: Bumper Rear
Scratched
Over 100mm Thru Paint




6: Boot Lid
Scratched
UpTo 25mm Thru Paint



7: Qtr Panel nsr
Dented
With Paint Damage



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Door nsf
Dented
With Paint Damage



10: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



11: Wing nsf
Scratched
Over 25mm Thru Paint



12: Bumper Front
Scratched
Over 100mm Thru Paint



13: Bonnet
Scratched
Over 25mm Thru Paint



14: Lamp osr
Broken
Replace



15: Door osr
Dented
Over 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK