46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

FH63XRC

Vauxhall Corsa 1.4 SRi 3dr [AC]

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	12/02/2014	**VIN**	W0L0SDL08E6043461	**Gearbox**	MANUAL
Year	2014	**Body Style**	Hatchback	**Gears**	5
Mileage	72,137 Miles Warranted	**Keys**	1	**Doors**	3
		Service history	None		
Fuel Type	PETROL	**MOT Due**	26/08/2027		
Colour	RED				

Noisy engine
Car has a misfire
EML light is on car has been plugged in and detects cylinder 3 misfire detected

Tyres

NSF	MATADOR	6.0mm
NSR	MATADOR	6.0mm
OSF	MATADOR	6.0mm
OSR	MATADOR	6.0mm
Spare		

Features

- Cruise control
- Electric door mirrors
- Solid Paint
- Central locking
- Rear wiper
- Air conditioning
- ABS
- Remote central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Cloth seat trim
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Alloy wheels

Photos












28.10.2026










Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Wheel osr
Scratched
Over 50mm



6: Bumper Rear
Chipped
1 To 5




7: Boot Lid
Dented
2 Or Less UpTo 10mm



8: Wheel nsr
Scratched
Over 50mm




9: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



10: Qtr Panel nsr
Chipped
1 To 5



11: Door nsf
Chipped
Edge Chip



12: Door nsf
Chipped
1 To 5



13: Wheel nsf
Scratched
Over 50mm



14: Wing nsf
Chipped
1 To 5



15: Bonnet
Chipped
Multiple Chips



16: Bumper Front
Chipped
Multiple Chips



17: Roof
Chipped
1 To 5



18: Bumper Rear
Scratched
25 to 100mm Thru Paint



19: Qtr Panel osr
Dented
Between 10mm + 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK