46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GY67XRD

Audi A5 2.0 TFSI Quattro S Line 2dr S Tronic

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	30/11/2017	**Keys**	2	**CAP Clean**	£10,750.00
Year	2017	**Service history**	Yes	**CAP Average**	£9,750.00
Mileage	81,454 Miles Warranted	**Service documents**	Printout	**CAP Below**	£8,725.00
Fuel Type	PETROL	**Number of stamps**	5	**Gearbox**	SEMI AUTO
Colour	WHITE	**Last service date**	28/10/2025	**Gears**	7
VIN	WAUZZZF57HN004370	**Last service miles**	77,080	**Doors**	2
Body Style	Convertible	**MOT Due**	27/10/2027		

£90 ADDITIONAL FEE
LAST SERVICE 28/10/2025 @ 77,080 MILES (5 SERVICES)

Tyres

NSF	BUDGET	7.0mm
NSR	BUDGET	7.0mm
OSF	BUDGET	7.0mm
OSR	BUDGET	7.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Telephone
- Electric sunroof
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Heated front seat
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels


Photos





















Eastbourne Car Auctions

Condition Check



Damage Photos




1: Wheel osf
Scratched
Over 50mm



2: Sill Panel Trim os
Scratched (Painted)
Over 25mm Thru Paint



3: Door osf
Dented
Between 10mm + 30mm



4: Door osf
Chipped
1 To 5



5: Door osf
Chipped
Edge Chip



6: Qtr Panel osr
Dented
With Paint Damage



7: Wheel osr
Scratched
Over 50mm



8: Bumper Rear
Poor Previous Repair
Paint Flake



9: Qtr Panel nsr
Dented
With Paint Damage



10: Wheel nsr
Scratched
Over 50mm



11: Sill Panel Trim ns
Broken
Replace



12: Door nsf
Dented
With Paint Damage




13: Wing nsf
Dented
With Paint Damage



14: Wheel nsf
Scratched
Over 50mm



15: Bonnet
Chipped
1 To 5



16: Screen Front
Chipped
UpTo 10mm



17: Door Pad osf
Scuffed
UpTo 25mm



18: Bumper Front
Cracked
Over 25mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		

Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		