46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

WL17BXV

Hyundai I10 1.2 SE 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	31/05/2017	**Body Style**	Hatchback	**Last service miles**	42,788
Year	2017	**Keys**	2	**MOT Due**	04/06/2027
Mileage	45,257 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	5
Colour	WHITE	**Number of stamps**	6	**Doors**	5
VIN	NLHA851CLHZ335803	**Last service date**	04/06/2026		

Last Service - 04.06.2026 at 42788 miles (6 Services)

Tyres

NSF	HANKOOK	4.0mm
NSR	HANKOOK	5.0mm
OSF	HANKOOK	4.0mm
OSR	HANKOOK	5.0mm
Spare		

Features

- Bluetooth connection
- Radio/CD
- Front electric windows
- ABS
- Tyre pressure monitor
- Steel wheels
- Rear parking sensor
- Body coloured bumpers
- Rear electric windows
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking
- Telephone
- Air conditioning
- Solid Paint
- Traction control
- Cloth seat trim

Photos














BACK
RADIO
MEDIA
PHONE
TA SCAN
SETUP CLOCK
MENU
FM2
11:18
Pop M
102.40
Heart
SEEK TRACK
FOLDER
1 RPT
2 RDM
3
4
5
6
PASSENGER AIR BAG



Condition Check



Damage Photos



1: Wing osf
Dented
With Paint Damage



2: Door osf
Dented
With Paint Damage



3: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



4: Door osr
Chipped
1 To 5



5: Door osr
Dented
Between 10mm + 30mm



6: Boot Lid
Chipped
1 To 5



7: Bumper Rear
Chipped
Multiple Chips



8: Door nsr
Chipped
1 To 5



9: Door nsf
Chipped
1 To 5



10: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



11: Bumper Front
Scratched
Over 100mm Thru Paint



12: Bonnet
Chipped
Multiple Chips

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK