46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GV65HPY

Honda CR-V 1.6 i-DTEC 160 EX 5dr Auto

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	21/12/2015	**Body Style**	Estate	**Last service miles**	97,859
Year	2015	**Keys**	2	**MOT Due**	20/12/2026
Mileage	103,066 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
Fuel Type	DIESEL	**Service documents**	Service Book	**Gears**	9
Colour	BROWN	**Number of stamps**	8	**Doors**	5
VIN	SHSRE6890FU521372	**Last service date**	16/12/2025		

£90 ADDITIONAL FEE
Last Service - 16.12.2025 at 97859 miles (8 Services)
Stop / start not working

Tyres

NSF	GOODYEAR	6.0mm
NSR	YOKOHAMA	5.0mm
OSF	GOODYEAR	6.0mm
OSR	YOKOHAMA	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Cruise control
- Park assist camera
- Service indicator
- Electric door mirrors
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels

Photos








GV65 HPY










Ready to Navigate









60 mph
80
40
100
20
120
0
140


Check Your Surroundings

Condition Check



Damage Photos



1: Seat Back Cover osf
Scuffed
Over 25mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Chipped
1 To 5



4: Wing nsf
Chipped
1 To 5



5: Wheel nsf
Scratched
Over 50mm



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsf
Chipped
1 To 5



8: Door nsf
Dented
Between 10mm + 30mm



9: Door nsr
Scratched
UpTo 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: B Post ns
Dented
Between 10mm + 30mm



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Qtr Panel osr
Dented
Over 30mm



14: Wheel osr
Scratched
Up To 50mm



15: Door osr
Chipped
Edge Chip



16: Door osf
Chipped
1 To 5



17: Wing osf
Chipped
1 To 5



18: Wheel osf
Scratched
Over 50mm



19: Aperture Seal osf
Broken
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK