46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

AK10VFY

Land Rover Freelander 2.2 Td4 HSE 5dr Auto

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	24/03/2010	**Body Style**	Estate	**Last service miles**	150,868
Year	2010	**Keys**	3	**MOT Due**	15/03/2027
Mileage	154,084 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
Fuel Type	DIESEL	**Service documents**	Service Book	**Gears**	6
Colour	GREY	**Number of stamps**	13	**Doors**	5
VIN	SALFA2AB2AH190821	**Last service date**	13/03/2026		

LAST SERVICE 13/03/26 @ 150,868 MILES (13 SERVICES)
CAMBELT & WATER PUMP REPLACED 25/01/21 @ 115,957 MILES

Tyres

NSF	PIRELLI	5.0mm
NSR	PIRELLI	6.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	6.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Radio/CD
- Air conditioning
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Heated front seat
- Telephone
- Electric sunroof
- Electrically adjustable passenger seat
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Front electric windows
- ABS
- Central locking
- Rear electric windows
- Drivers airbag
- Remote central locking
- Rear headrests
- Passenger airbag
- Leather seat trim

Photos























Eastbourne Car Auctions

Condition Check




Damage Photos




1: Wheel osf
Scratched
Up To 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
Multiple Chips



4: Door osr
Chipped
1 To 5



5: Door osr
Scratched
UpTo 25mm Thru Paint



6: Wheel osr
Scratched
Up To 50mm



7: Qtr Panel osr
Chipped
1 To 5



8: Bumper Rear
Poor Previous Repair
Paint Flake



9: Qtr Panel nsr
Poor Previous Repair
Poor Paint



10: Wheel nsr
Scratched
Over 50mm



11: Door nsr
Poor Previous Repair
Paint Flake



12: Door nsf
Scratched
Over 25mm Thru Paint



13: Wing nsf
Scratched
Over 25mm Thru Paint



14: Wheel nsf
Scratched
Over 50mm




15: Bumper Front
Scratched
UpTo 25mm Thru Paint



16: Bumper Front
Chipped
Multiple Chips



17: Bonnet
Chipped
1 To 5



18: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		