46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

NG59HFD

Ford Fiesta 1.4 Titanium 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	29/01/2010
Year	2010
Mileage	121,010 Miles Warranted
Fuel Type	PETROL
Colour	SILVER
VIN	WF0JXXWPJJ9E50847

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	11
Last service date	23/01/2026

Last service miles	115,949
MOT Due	19/02/2027
Gearbox	MANUAL
Gears	5
Doors	5

£90 ADDITIONAL FEE
Last Service - 230.1.2026 at 115949 miles (11 Services)
Timing Belt Replaced 03.02.2022 @ 87843 Miles Front and rear suspension knocking

Tyres

NSF	BUDGET	5.0mm
NSR	COOPER TIRES	Damaged
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features

- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos
















Condition Check



Damage Photos



1: Tyre nsr
Damaged
Replace



2: Bonnet
Dented
With Paint Damage



3: Bumper Front
Dented
With Paint Damage



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Dented
Between 10mm + 30mm



6: Door nsf
Chipped
Edge Chip



7: Door nsr
Chipped
Edge Chip



8: Wheel nsr
Scratched
Over 50mm



9: Bumper Rear
Poor Previous Repair
Poor Paint



10: B Post ns
Dented
2 Or Less UpTo 10mm



11: B Post os
Dented
Between 10mm + 30mm



12: Qtr Panel osr
Poor Previous Repair
Poor Paint



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Scratched
Over 25mm Thru Paint



15: Door osf
Chipped
Edge Chip



16: Wing osf
Rusted
Over 5mm



17: Wheel osf
Scratched
Over 50mm



18: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK