46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

CE12XAD

Ford Focus 1.6 125 Zetec 5dr

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	06/04/2012	**VIN**	WF0KXXGCBKBU58884	**Gearbox**	MANUAL
Year	2012	**Body Style**	Hatchback	**Gears**	5
Mileage	91,389 Miles Warranted	**Keys**	2	**Doors**	5
		Service history	None		
Fuel Type	PETROL	**MOT Due**	Expired		
Colour	GREY				

£100 ADDITIONAL FEE
No service history
MOT EXPIRED Nsf window does not work

Tyres

NSF	LAUFENN	1.0mm
NSR	LAUFENN	5.0mm
OSF	LAUFENN	2.0mm
OSR	LAUFENN	5.0mm
Spare		

Features

- Bluetooth connection
- Radio/CD
- Front armrest
- ABS
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Alloy wheels

Photos

















S471







Condition Check



Damage Photos



1: Wing osf
Dented
Over 30mm



2: Door osf
Chipped
1 To 5



3: Door osf
Dented
2 Or Less UpTo 10mm



4: Door osr
Dented
Over 30mm



5: Door osf
Chipped
Edge Chip



6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Wheel osr
Scratched
Over 50mm



8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Tailgate
Scratched
UpTo 25mm Thru Paint



10: Qtr Panel nsr
Dented
Over 30% Of Panel



11: Door nsr
Dented
With Paint Damage



12: Door nsf
Chipped
1 To 5



13: Wheel nsf
Scratched
Over 50mm



14: Bumper Front
Scratched
Over 100mm Thru Paint



15: Bonnet
Chipped
1 To 5



16: Seat Back Cover osf
Torn
UpTo 3mm



17: Other
N/A
N/A



18: Lamp nsr
Broken
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	Fault	Radio	OK
		Steering	OK