46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

KY62HXW

Mercedes-Benz E Class E250 CDI BlueEFFICIENCY Sport 2dr Tip Auto

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	26/09/2012	**Body Style**	Convertible	**Last service miles**	113,611
Year	2012	**Keys**	2	**MOT Due**	29/03/2027
Mileage	119,768 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
Fuel Type	DIESEL	**Service documents**	Printout	**Gears**	7
Colour	SILVER	**Number of stamps**	8	**Doors**	2
VIN	WDD2074032F185013	**Last service date**	07/03/2026		

£90 ADDITIONAL FEE
Last Service - 07.03.26 @ 113611 miles (8 services)

Tyres

NSF	BUDGET	3.0mm
NSR	ROTALLA	2.0mm
OSF	BUDGET	3.0mm
OSR	ROTALLA	2.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Cruise control
- Telephone
- Electric sunroof
- Front electric windows
- ABS
- Central locking
- Front parking sensor
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Heated front seat
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Leather seat trim


Photos












342
COLOURS AVAILABLE




Condition Check



Damage Photos




1: Seat Base Cover osf
Scuffed
Over 25mm



2: Wheel osf
Corroded
Light



3: Door osf
Chipped
Edge Chip



4: Qtr Panel osr
Scratched
Over 25mm Thru Paint



5: Wheel osr
Corroded
Light




6: Bumper Rear
Poor Previous Repair
Poor Paint



7: Boot Lid
Chipped
1 To 5



8: Wheel nsr
Corroded
Light



9: Door nsf
Chipped
1 To 5



10: Other
N/A
N/A



11: Wheel nsf
Corroded
Light



12: Bumper Front
Poor Previous Repair
Paint Flake



13: Bonnet
Chipped
1 To 5



14: A Post os
Chipped
1 To 5



15: Other
N/A
N/A
Front parking sensor missing

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Poor	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	Fault	Radio	OK
Windows	Fault	Steering	OK