46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LJ17KZT

Honda Fit 3 HYBRID

Imported

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	01/07/2023	**VIN**	GP51302472	**Number of stamps**	1
Year	2017	**Body Style**	Hatchback	**Last service date**	22/05/2022
Mileage	42,943 Km Warranted	**Keys**	2	**Last service miles**	40,253
Fuel Type	HYBRID ELECTRIC	**Service history**	Yes	**MOT Due**	20/07/2027
Colour	BLUE	**Service documents**	Printout	**Doors**	5

First registered in UK in 2023 - previously registered overseas
Last Service - 22.05.2024 at 40253 miles (1 Services)
Mileage listed as both miles and km

Tyres

NSF	RAPID	5.0mm
NSR	RAPID	5.0mm
OSF	RAPID	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features

- Navigation system
- Telephone
- Air conditioning
- Drivers airbag
- Remote central locking
- Park assist camera
- Radio/CD
- Climate control
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Metallic Paint
- Traction control
- Leather seat trim
- Rear wiper
- Electric door mirrors
- ABS
- Central locking
- Steel wheels


Photos

















Condition Check



Damage Photos



1: Door osf
Chipped
Edge Chip



2: Qtr Panel osr
Dented
Between 10mm + 30mm



3: Bumper Rear
Scratched
25 to 100mm Thru Paint



4: Door nsf
Chipped
1 To 5



5: A Post os
Chipped
1 To 5



6: Bonnet
Poor Previous Repair
Poor Colour



7: Sill ns
Dented
Over 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK