46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

FV11PMY

Skoda Fabia 1.2 TSI SE 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	15/04/2011
Year	2011
Mileage	89,251 Miles Warranted
Fuel Type	PETROL
Colour	GREEN
VIN	TMBFM25J4B3178376
Body Style	Hatchback

Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	3
Last service date	23/03/2026
Last service miles	88,575
MOT Due	16/02/2027

CAP Clean	£1,400.00
CAP Average	£1,000.00
CAP Below	£600.00
Gearbox	MANUAL
Gears	5
Doors	5

£90 ADDITIONAL FEE
Last Service - 23.03.2026 at 88575 miles (3 Services)

Tyres

NSF	AUTOGREEN	4.0mm
NSR	FIRESTONE	3.0mm
OSF	AUTOGREEN	4.0mm
OSR	FIRESTONE	5.0mm
Spare		

Features

- Rear wiper
- Air conditioning
- ABS
- Central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Electric door mirrors
- Metallic Paint
- Traction control
- Alloy wheels

Photos









FV11 PMY






BBC R4 93.5 MHz



296







Condition Check



Damage Photos



1: Wing osf
Scratched
UpTo 25mm Thru Paint



2: Door osf
Scratched
Over 25mm Thru Paint



3: Roof
Poor Previous Repair
Paint Flake



4: Door osr
Dented
Over 30mm



5: Qtr Panel osr
Chipped
1 To 5



6: Wheel osr
Scratched
Over 50mm



7: Bumper Rear
Poor Previous Repair
Paint Flake



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Up To 50mm



10: Door nsr
Rusted
UpTo 5mm



11: Door nsf
Chipped
Multiple Chips



12: Wheel nsf
Scratched
Over 50mm



13: Bumper Front
Scratched
Over 100mm Thru Paint



14: Bumper Front Moulding
Broken
Replace



15: Bonnet
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK