46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

BD14NNW

Audi A4 2.0 TDI 150 S Line 4dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	21/05/2014	**Body Style**	Saloon	**Last service miles**	103,085
Year	2014	**Keys**	2	**MOT Due**	29/12/2026
Mileage	116,461 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	DIESEL	**Service documents**	Printout	**Gears**	6
Colour	BLACK	**Number of stamps**	6	**Doors**	4
VIN	WAUZZZ8K3EA150755	**Last service date**	30/12/2024		

£90 ADDITIONAL FEE
LAST SERVICE 30/12/2024 @ 103,085 MILES (6 SERVICES)

Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	4.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Cruise control
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- ABS
- Central locking
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Heated front seat
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Leather seat trim

Photos


















Condition Check




Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Scratched
Over 25mm Thru Paint




3: Door osf
Chipped
Edge Chip



4: Door osf
Dented
2 Or Less UpTo 10mm



5: Door osr
Chipped
Edge Chip



6: Bumper Rear
Poor Previous Repair
Poor Paint



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




8: Wheel nsr
Scratched
Over 50mm




9: Door nsr
Chipped
1 To 5




10: Wheel nsf
Scratched
Over 50mm



11: Wing nsf
Chipped
1 To 5




12: Bumper Front
Poor Previous Repair
Paint Flake




13: Other
N/A
N/A



14: Bonnet
Chipped
Multiple Chips



15: Screen Front
Chipped
UpTo 10mm



16: Roof
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK