46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

BW11EWD

Volkswagen Passat 2.0 TDI Bluemotion Tech SE 5dr

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	28/07/2011	**Body Style**	Estate	**Last service miles**	108,468
Year	2011	**Keys**	2	**MOT Due**	Expired
Mileage	115,812 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	DIESEL	**Service documents**	Service Book	**Gears**	6
Colour	BRONZE	**Number of stamps**	9	**Doors**	5
VIN	WVWZZZ3CZCE021211	**Last service date**	11/06/2025		

£100 ADDITIONAL FEE
MOT EXPIRED
Last Service - 11.06.2025 at 108468 miles (9 Services)

Tyres

NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	Damaged
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Central locking
- Heated front seat
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Leather seat trim

Photos


























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
Edge Chip



3: Door osf
Chipped
1 To 5



4: Door osr
Scratched
Over 25mm Thru Paint



5: Wheel osr
Scratched
Over 50mm



6: Qtr Panel osr
Chipped
1 To 5



7: Bumper Rear
Scratched
Over 100mm Thru Paint



8: Wheel nsr
Scratched
Up To 50mm



9: Qtr Panel nsr
Chipped
1 To 5



10: Door nsr
Scratched
UpTo 25mm Thru Paint



11: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



12: Wheel nsf
Scratched
Over 50mm



13: Wing nsf
Chipped
1 To 5



14: Bumper Front
Scratched
25 to 100mm Thru Paint



15: Bonnet
Chipped
Multiple Chips



16: Screen Front
Chipped
UpTo 10mm



17: Fascia Trim
Missing
Replace



18: Tyre nsr
Damaged
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK