46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LA54CFM

Peugeot 206 SPORT

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	10/02/2005	**VIN**	VF32CHFXF44507011	**Gearbox**	MANUAL
Year	2005	**Body Style**	Hatchback	**Gears**	5
Mileage	71,225 Miles Warranted	**Keys**	2	**Doors**	3
Fuel Type	PETROL	**Service history**	None		
Colour	RED	**MOT Due**	10/02/2027		

£100 ADDITIONAL FEE
NO SERVICE HISTORY

Tyres

NSF	PIRELLI	5.0mm
NSR	NEXEN	5.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	5.0mm
Spare		

Features

- Rear wiper
- Air conditioning
- Solid Paint
- Central locking
- Radio/CD
- Climate control
- ABS
- Remote central locking
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Cloth seat trim
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Alloy wheels




Photos












Condition Check




Damage Photos



1: Wheel osf
Scratched
Over 50mm




2: Wing osf
Scratched
UpTo 25mm Thru Paint



3: Door osf
Scratched
Over 25mm Thru Paint



4: Qtr Panel osr
Chipped
1 To 5



5: Bumper Rear
Scratched
25 to 100mm Thru Paint




6: Tailgate Pad
Scuffed
Over 25mm



7: Qtr Panel nsr
Poor Previous Repair
Poor Paint



8: Door nsf
Scratched
UpTo 25mm Thru Paint



9: Door nsf
Dented
Between 10mm + 30mm



10: Wing nsf
Scratched
Over 25mm Thru Paint




11: Wheel nsf
Scratched
Over 50mm



12: Bumper Front
Scratched
Over 100mm Thru Paint



13: Bonnet
Chipped
1 To 5



14: Screen Front
Chipped
UpTo 10mm



15: Spoiler Rear
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK