46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

WV58YDR

Toyota Verso 1.8 VVT-i SR 5dr

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	05/09/2008	**Body Style**	MPV	**Last service miles**	26,321
Year	2008	**Keys**	2	**MOT Due**	17/07/2027
Mileage	118,749 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Printout	**Gears**	5
Colour	GREY	**Number of stamps**	1	**Doors**	5
VIN	NMTER16RX0R136946	**Last service date**	16/06/2011		

£100 ADDITIONAL FEE
Last Service - 16.06.2011 at 26321 miles (1 Services)

Tyres

NSF	BUDGET	5.0mm
NSR	INVOVIC	5.0mm
OSF	BUDGET	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features

- Rear parking sensor
- Electric door mirrors
- Front electric windows
- ABS
- Remote central locking
- Rear wiper
- Air conditioning
- Rear electric windows
- Drivers airbag
- Cloth seat trim
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Alloy wheels
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Central locking

Photos











FM1 CH2 Hits









0pm
.co.uk



Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Scratched
Over 25mm Thru Paint



3: Door osr
Dented
With Paint Damage



4: Sill os
Scratched
Over 25mm Thru Paint



5: Wheel osr
Scratched
Over 50mm



6: Qtr Panel osr
Chipped
1 To 5



7: Bumper Rear
Cracked
Over 25mm



8: Other
N/A
N/A
Rear parking sensor missing



9: Boot Lid
Dented
Over 30mm



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Door nsr
Dented
With Paint Damage



13: Door nsf
Dented
Over 30mm



14: Wing nsf
Dented
With Paint Damage



15: Wheel nsf
Scratched
Over 50mm



16: Bumper Front
Scratched
Over 100mm Thru Paint



17: Bonnet
Chipped
1 To 5



18: Seat Base Cover osf
Scuffed
UpTo 25mm



19: Door osf
Dented
Over 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	Fault	Radio	OK
		Steering	OK