46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

PJ12TZP

Volkswagen UP 1.0 Move Up 3dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	23/07/2012	**Body Style**	Hatchback	**MOT Due**	11/04/2027
Year	2012	**Service history**	Yes	**Gearbox**	MANUAL
Mileage	65,335 Miles Warranted	**Service documents**	Service Book	**Gears**	5
Fuel Type	PETROL	**Number of stamps**	2	**Doors**	3
Colour	SILVER	**Last service date**	11/07/2015		
VIN	WVWZZZAAZDD011227	**Last service miles**	28,010		

£100 ADDITIONAL FEE
Last Service - 11.07.2015 at 28010 miles (2 Services)

Tyres

NSF	HANKOOK	6.0mm
NSR	HANKOOK	6.0mm
OSF	HANKOOK	6.0mm
OSR	HANKOOK	5.0mm
Spare		

Features

- Rear wiper
- Front electric windows
- Drivers airbag
- Remote central locking
- Radio/CD
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Body coloured bumpers
- Metallic Paint
- Traction control
- Steel wheels
- Air conditioning
- ABS
- Central locking

Photos











FM
87.5MHz
1 2 3 4 5 6










Condition Check



Damage Photos



1: Wing osf
Scratched
UpTo 25mm Thru Paint



2: Door osf
Chipped
1 To 5



3: Qtr Panel osr
Dented
Over 30mm



4: Bumper Rear
Cracked
Over 25mm



5: Qtr Panel nsr
Dented
With Paint Damage



6: Door nsf
Dented
With Paint Damage



7: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



8: A Post ns
Dented
With Paint Damage



9: Bumper Front
Scratched
25 to 100mm Thru Paint



10: Bonnet
Chipped
1 To 5



11: Wheel Trim nsf
Missing
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK