46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**LH73AKG**

## Hyundai Kona 1.6 GDi Hybrid N Line S 5dr DCT

nama GRADE 2

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Margin |
| **V5** | Buyer To Apply |

### Details

| | | | | | |
|---|---|---|---|---|---|
| **Reg. date** | 18/09/2023 | **Body Style** | Hatchback | **Last service miles** | 20,292 |
| **Year** | 2023 | **Keys** | 2 | **Gearbox** | SEMI AUTO |
| **Mileage** | 21,217 Miles Warranted | **Service history** | Yes | **Gears** | 6 |
| **Fuel Type** | Hybrid Electric | **Service documents** | Printout | **Doors** | 5 |
| **Colour** | GREY | **Number of stamps** | 3 | | |
| **VIN** | KMHHB8115RU013153 | **Last service date** | 12/08/2026 | | |

£100 ADDITIONAL FEE
NO V5
LAST SERVICE 12/08/2026 @ 20,292 MILES (3 SERVICES, ALL MAIN DEALER)

### Tyres

| | | |
|---|---|---|
| **NSF** | DUNLOP | 6.0mm |
| **NSR** | KUMHO | 5.0mm |
| **OSF** | DUNLOP | 6.0mm |
| **OSR** | FALKEN | 5.0mm |
| **Spare** | | |

## Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Air conditioning
- Front parking sensor
- PAS
- Digital radio
- Electrically adjustable drivers seat
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable passenger seat
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- Front armrest
- Rear electric windows
- Solid Paint
- Isofix child seat anchor points
- Central locking
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Partial leather seat trim

## Photos









JP72 EGP


HYBRID








0
MPH
Low pressure
Check all tyres, then
store the tyre pressures
ECO
READY
P







SYNC
A/C
OFF
AUTO


1:37 PM

# Condition Check




## Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5




3: Wheel nsf
Scratched
Over 50mm




4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



5: Door nsf
Chipped
1 To 5



6: Wheel nsr
Scratched
Up To 50mm



7: Bumper Rear
Chipped
1 To 5



8: Door osr
Chipped
Edge Chip



9: Door osf
Chipped
Edge Chip



10: Wheel osf
Scratched
Over 50mm

**Interior**

| | | | |
|---|---|---|---|
| **Carpet Condition** | Average | **Upholstery Condition** | Average |
| **Seat Condition** | Average | **Odour** | No |

## Vehicle Inspection Report

**Disclaimer**
**Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.**
**Additional fees may apply to some vendors.**
**Please note buyers rate increase from 01/01/2025**

| | | | |
|---|---|---|---|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| Sat nav | OK | Steering | OK |