46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

HXZ6016

Kia Sportage 1.6T GDi GT-Line 5dr DCT Auto [AWD]

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	24/02/2017
Year	2017
Mileage	56,367 Miles Warranted
Fuel Type	PETROL
Colour	SILVER
VIN	U5YPK816WHL247333

Body Style	Estate
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	5
Last service date	26/01/2022

Last service miles	19,780
MOT Due	27/01/2027
Gearbox	SEMI AUTO
Gears	7
Doors	5

£100 ADDITIONAL FEE
Last Service - 26.01.2022 at 19780 miles (5 Services) Eml light is on car been pluton and detected unable to engage gear 1

Tyres

NSF	WANLI	5.0mm
NSR	WANLI	5.0mm
OSF	WANLI	5.0mm
OSR	WANLI	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Service indicator
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos








HXZ 6016


KIA






712










Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Bumper Front
Scratched
UpTo 25mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm




6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Door nsr
Dented
Between 10mm + 30mm



10: Qtr Panel nsr
Chipped
1 To 5



11: Boot Lid
Scratched
UpTo 25mm Thru Paint




12: Bumper Rear
Chipped
1 To 5



13: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Chipped
1 To 5



16: Door osf
Chipped
Multiple Chips



17: Wing osf
Chipped
1 To 5



18: Wing osf
Dented
2 Or Less UpTo 10mm



19: Wheel osf
Scratched
Over 50mm



20: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK