46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

DP70VPT

Nissan Qashqai 1.3 DiG-T 160 [157] N-Connecta 5dr DCT Glass Roof

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	31/12/2020	**Body Style**	Hatchback	**Last service miles**	92,467
Year	2020	**Keys**	2	**MOT Due**	26/10/2027
Mileage	93,963 Miles Warranted	**Service history**	Yes	**Gearbox**	SEMI AUTO
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	7
Colour	SILVER	**Number of stamps**	7	**Doors**	5
VIN	SJNFFAJ11U2930315	**Last service date**	01/09/2026		

£100 ADDITIONAL FEE
Last Service - 01.09.26 @ 92467 miles (7 services) Gearbox judders

Tyres

NSF	BUDGET	4.0mm
NSR	MICHELIN	3.0mm
OSF	WESTLAKE	3.0mm
OSR	BUDGET	2.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels


Photos









DP70 VPT




Traffic Sign
93963miles




DAB
2:48
Source
DAB Menu
Magic Musicals
Loading...












Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Chipped
1 To 5



3: Door osf
Scratched
Over 25mm Thru Paint



4: Wheel osr
Corroded
Light



5: Door osr
Chipped
Edge Chip



6: Bumper Rear
Chipped
1 To 5



7: Wheel nsr
Corroded
Light



8: Door nsr
Chipped
1 To 5



9: Door nsf
Chipped
1 To 5



10: Wheel nsf
Corroded
Light



11: Bumper Front
Scratched
25 to 100mm Thru Paint



12: Bumper Front
Chipped
Multiple Chips



13: Bonnet
Chipped
1 To 5



14: Wing Front Arch Extension os
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	Fault
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		