46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LB71XOX

Volkswagen Tiguan 1.4 TSI eHybrid R-Line 5dr DSG

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	29/12/2021	**Body Style**	Estate	**Last service miles**	44,781
Year	2021	**Keys**	2	**MOT Due**	28/12/2026
Mileage	50,201 Miles Warranted	**Service history**	Yes	**Gearbox**	SEMI AUTO
Fuel Type	HYBRID ELECTRIC	**Service documents**	Printout	**Gears**	7
Colour	BLUE	**Number of stamps**	5	**Doors**	5
VIN	WVGZZZ5NZNW401082	**Last service date**	31/03/2026		

£100 ADDITIONAL FEE
LAST SERVICE 31//03/2026 @ 44,781 MILES (5 SERVICES) Type 2 and 3 pin charging cables in boot

Tyres

NSF	PIRELLI	4.0mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	4.0mm
OSR	PIRELLI	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Telephone
- Electric sunroof
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos









LB71 XDX


LB71 XDX






BBC Radio1Xtra




15:26
P
0
mph
Please switch on light.
READY












Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Poor Previous Repair
Poor Paint



3: Door osr
Chipped
1 To 5



4: Door osr
Dented
2 Or Less UpTo 10mm



5: Bumper Rear
Scratched
Up To 25mm Thru Paint




6: Bumper Rear
Chipped
1 To 5



7: Wheel nsr
Scratched
Over 50mm



8: Door nsr
Chipped
1 To 5



9: Door nsr
Dented
2 Or Less UpTo 10mm



10: Wheel nsf
Scratched
Over 50mm



11: Bonnet
Chipped
1 To 5



12: Seat Back Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		

Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		