46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

KT68VGE

Kia Niro 1.6 GDi Hybrid 2 5dr DCT

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	08/01/2019	**VIN**	KNACC81CVK5237313	**Gearbox**	SEMI AUTO
Year	2019	**Body Style**	Estate	**Gears**	6
Mileage	41,080 Miles Warranted	**Keys**	2	**Doors**	5
		Service history	None		
Fuel Type	HYBRID ELECTRIC	**MOT Due**	24/01/2027		
Colour	WHITE				

£100 ADDITIONAL FEE
NO SERVICE HISTORY Hand controls fitted to steering wheel column

Tyres

NSF	BUDGET	5.0mm
NSR	MICHELIN	Damaged
OSF	MICHELIN	Damaged
OSR	ZEETEX	5.0mm
Spare		

Features

- Bluetooth connection
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Steel wheels
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim

Photos









KY68 VDE


KIA


264mi
41080mi



12:33
DAB/FM
RADIO
MEDIA
MAP
NAV
SEEK
TRACK
SETUP



ECO hybrid
RADIO
MEDIA
MAP
NAV





WARNING
Hand Controls


KIA










Condition Check



Damage Photos



1: Tyre osf
Damaged
Replace




2: Tyre nsr
Damaged
Replace



3: Bonnet
Chipped
1 To 5



4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



6: Door nsf
Poor Previous Repair
Poor Paint



7: Door nsr
Dented
With Paint Damage



8: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Boot Lid
Chipped
1 To 5




11: Door osr
Chipped
Edge Chip



12: Door osf
Chipped
Edge Chip



13: Wing osf
Scratched
Over 25mm Thru Paint



14: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK